IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of: Collin et al.

Patent No. 6,874,134 **Issued:** March 29, 2005

Application No. 09/731,535

Filed: December 6, 2000 Confirmation No. 2069

For: CONVERSION OF AN HDL

SEQUENTIAL TRUTH TABLE TO

GENERIC HDL ELEMENTS

Examiner: Annette M. Thompson

Art Unit: 2825

Attorney Reference No. 1011-64527-01

Filed via EFS June 20, 2007.

CERTIFICATE OF FILING

I hereby certify that this paper and the documents referred to as being attached or enclosed herewith are being filed via EFS on the date shown below.

Attorney or Agent

for Applicant(s) /Justin D. Wagner/

Date Filed __June 20, 2007

REQUEST FOR CERTIFICATE OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In the Specification:

Column 5, line 20, "generic HOL" should be --generic HDL--.

Column 8, line 47, "the state 0001is" should be --the state 0001 is--.

Column 10, line 67, "clock 15, signal" should be --clock 15 signal--.

In the Claims:

Column 16, line 19, "EUR 0X" should be --EUR0X--.

Column 20, line 22, "for the generic HDL," should be --for the generic HDL--.

Column 22, line 21, "function Fd 0." should be --function Fd=0.--.

All of the above errors are attributable to the Patent Office, and a Certificate of Correction is enclosed to make formal notice of the errors in the referenced patent.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

By /Justin D. Wagner/ Justin D. Wagner

Registration No. 54,519

One World Trade Center, Suite 1600 121 S.W. Salmon Street Portland, Oregon 97204 Telephone: (503) 595-5300

Facsimile: (503) 595-5301

cc: Docketing

Staple Here Only

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,874,134

DATED : March 29, 2005

INVENTOR(S) : Collin et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5, line 20, "generic HOL" should be --generic HDL--.

Column 8, line 47, "the state 0001 is" should be -- the state 0001 is--.

Column 10, line 67, "clock 15, signal" should be --clock 15 signal--.

Column 16, line 19, "EUR 0X" should be --EUR0X--.

Column 20, line 22, "for the generic HDL," should be --for the generic HDL--.

Column 22, line 21, "function Fd 0." should be --function Fd=0.--.

121 SW Salmon Street Portland, Oregon 97204 PATENT NO. 6,874,134 No. of add'l copies